ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	5	Jakkuru

Street ID	Street Name	Significant Landmark
W1108, W2009, W2015, W2001, W1110, W1961, W1116, W	NA, 9th Crs Ashirwad Colony, 1st Main Rd 10th Crs Bank Avenue Horamavu, 2nd Main Rd 9th Crs Bank Ave	Basavalingappa nagara

Segment No.	Total Length (m)
5/C-W1108/S092413	674.71

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	363.25	77.631298	13.076689	77.630686	13.073462	Hegadenagara main road	Basavaligappa nagara
2	311.46	77.630724	13.076798	77.633567	13.076401	Hegadenagara main road	Basavalingapp anagara

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Improvements to roads and drainat Basavalingappanagara in ward no. 05 byatarayanapura sub division	4900000	2015-16

Year	Type of Work	Other Work Type
2015 - 2016	Asphalting	

Tender	Work Details	Job No. / Work Code
Tender		005-16-000010

Work Order No.	Work Order Date	Period of Extention
EE/BTP/BBMP/PMT/218/15-16	16/02/2017	

Defect Liability Period From	Defect Liability Period To	Multiple road involved with the same Job No/ Work Code #
25/06/2017	25/06/2018	No

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
K. Narasimharaju		0.00

Phone No.	E-Mail ID
9448083246	

Zone: YELAHANKA **Ward No:** 5 **Ward Name:** Jakkuru **Street ID:** W1108, W2009, W2015, W2001, W1110, W

ಸಹಾಯಕ ಅಭಿಯಂತರರು
ಬಿ.ಬಿ.ಎಂ.ಪಿ. ಬ್ಯಾಟರಾಯನಪುರ ಉಪ ವಿಭಾಗ

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಬ್ಯಾಟರಾಯನಪುರ ಉಪ ವಿಭಾಗ
ಬಿ.ಬಿ.ಎಂ.ಪಿ. ಬೆಂಗಳೂರು-26

d Inspection Details

Number of Trees	Any Other Information	Name
0		chandrappa h
Date of Inspection	**Remarks**	
27/10/2017		

Category	Image	Photo Remark
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	Parameshwaraiah	27/10/2017	26/11/2017	Approved

Zone: YELAHANKA **Ward No:** 5 **Ward Name:** Jakkuru **Street ID:** W1108, W2009, W2015, W2001, W1110, W

ಸಹಾಯಕ ಅಭಿಯಂತರರು
ಬಿ.ಬಿ.ಎಂ.ಪಿ. ಬ್ಯಾಟರಾಯನಪುರ ಉಪ ವಿಭಾಗ

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಬ್ಯಾಟರಾಯನಪುರ ಉಪ ವಿಭಾಗ
ಬಿ.ಬಿ.ಎಂ.ಪಿ., ಬೆಂಗಳೂರು-26

	K.Vasu	27/10/2017	26/11/2017	Verify
E	H.T.Mohandas	27/10/2017	26/11/2017	Verify
AEE	B.s. Sridhar	27/10/2017	26/11/2017	Verify
AE	Chandrappa H	27/10/2017	26/11/2017	Mobil verification is done
AE	Chandrappa H	27/10/2017	26/11/2017	

Zone: YELAHANKA **Ward No:** 5 **Ward Name:** Jakkuru **Street ID:** W1108, W2009, W2015, W2001, W1110, W

ಸಹಾಯಕ ಅಭಿಯಂತರರು
ಬಿ.ಬಿ.ಎಂ.ಪಿ. ಬ್ಯಾಟರಾಯನಪುರ ಉಪ ವಿಭಾಗ

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಬ್ಯಾಟರಾಯನಪುರ ಉಪ ವಿಭಾಗ
ಬಿ.ಬಿ.ಎಂ.ಪಿ., ಬೆಂಗಳೂರು-26